Rock Island Arsenal Laboratory



HARD COPY MICROFICHE

TECHNICAL REPORT

CONTROL OF STRESS CORROSION-2nd Interim Report

Ву

APR 19 196

R. H. Wolff

Department of the Army Project No. 1C0-24401-A110

AMC Code No. 5025.11.84205

Copy No.

Report No. 65-152

IEL No. 1-9-100-2

Date 18 January 1965

FICE OF TECHNICAL SERVICES U. S. DEPARTMENT OF COMMERCE AND WASHINGTON 25, D. C.

R REQUIRED FOR REFERENCE

The findings in this report are not to be construed as an official Department of the Army position.

"Copies Available at Office of Technical Services \$.50

Report	No.	65-152
Copy No	o	

CONTROL OF STRESS CORROSION - 2ND INTERIM REPORT

3 v

7. Wolff
R. H. Wolff

Approved by:

G. O. INMAN

Acting Laboratory Director

18 January 1965

DA Project No. 1CO-24401-A110

AMC Code No. 5025.11.84205

Rock Island Arsenal Rock Island, Illinois

DDC Availability Notice:

Qualified requesters may obtain copies of this report from DDC.

ABSTRACT

This study of the control of stress corrosion cracking susceptibility of steels by application of protective coatings was designed to use abrasive blasted specimens to simulate more nearly the surfaces and conditions of a manufacturing operation. Bent beam specimens of 4130, 6150, and 18% nickel maraging steel were prepared at yield strength levels of 204, 231, and 316 ksi respectively for test at 75% of yield strength. Test atmospheres were outdoor, high humidity and salt stray (5%), and cycles of these alternating between salt spray, humidity and air. Cycle tests produced more rapid failure than single environments. Abrasive blasting extended the time to failure as compared to non-blasted uncoated specimens. Coated specimens were electroplated with zinc, zinc phosphatized, or brushed with zinc filled paint. Specimens of 4130 steel had not failed in over a year in outdoor exposure and 6 months in high humidity. Failures were noted with all the materials in cycle tests with indication of extended time to failure as a result of using zinc filled paint.

RECOMMENDATIONS

It is recommended that high strength materials be abrasive blasted prior to final finish application to make use of the improvement in stress corrosion cracking resistance noted in this work.

6! -152

CONTROL OF STRESS CORROSION - 2ND INTERIM REPORT

CONTENTS

	Page No.
Object	1
Introduction	1
Experimental Procedure	1
Results and Discussion	3
Conclusion	5
Literature References	8
Prior Report	9
Distribution	10

111

OBJECT

To study the reduction of susceptibility to stress corrosion cracking of high strength steels by use of protective coatings.

INTRODUCTION

This report is a continuation of a study (1) of the control of stress corrosion cracking susceptibility of steels by application of protective coatings. Work was designed to use abrasive blasted specimens to simulate more nearly the surfaces and conditions of a manufacturing operation. Initial work was conducted using specimens of aircraft quality 4130 alloy sheet steel, heat treated to approximately 200 ksi yield strength. Zinc was chosen as the basis of protective coating and was applied to abrasive blasted bent beam specimens as follows: by zinc electroplating, zinc phosphatizing, and by zinc dust dispersed in a vehicle. This work reports the results of tests.

EXPERIMENTAL PROCEDURE

Strips of 4130, 6150 and 18% nickel maraging steel were prepared as bent beam specimens .065 x 1 x 9 inches. Yield strength determinations were made (see Table I) and by the method of Phelps et al⁽²⁾ specimen lengths determined and cut to produce a tensile load of 75% of yield strength in the bent beam fixture. Specimens were uniformly steel grit blasted and coated except as tested bare for control. Tests were run in duplicate or triplicate as exposure space allowed.

Protective coatings used were from a hot zinc phosphatizing production bath, a conventional zinc cyanide electroplating solution, and a proprietary paint of zinc dust dispersed in a vehicle.

Test environments used were an outdoor semi-industrial exposure area approximately 300 feet from the Mississippi River; high humidity (100% RH at 100° F.); and 5% salt spray fog (Method 811.1 of Federal Test Method Standard 151a).

After the initial series of tests, additional tests were begun using cycles in which specimens were repeatedly alternated between salt spray, humidity cabinet and standing in air. These tests provided cycles such as 52 hours in salt spray, 52 hours in high humidity and 64 hours (over

TABLE I

TENSILE TEST OF BLASTED AND UNBLASTED SPECIMENS

Steel	Yield Strength ksi	Ultimate Strength ksi	Modulus of Elasticity x10
4130			
1 2 3B 4B 5 6 Average	205 206 204 203 206 201 204	251 252.5 252.5 252 252.5 252.5 252	28.9 30.0 30.2 29.7 29.6 29.7
6150			
15 2 35 4D 5 6 Average	228.7 232.5 231.8 228.3 236.1 231.6 231.5	244.3 244.6 245.3 241.2 247.7 245.8 244.8	3 0.

Specimens marked "B' were steel grit blasted.

18% Ni			
1	301.7	304	
2	324.3	326 .8	
ىد3	312.7	318.	
4E	324.	325.6	
Average	315.8	318.6	27.6

Mill Certified Analysis of 16% Ninkel Maraging Steel

. 3 <mark>2</mark> 7	. 33 5	. 0 3 7	.) 3 8	. 51 . 04 0	. Cr . JI 5	N1 18.95	. 13
Mo 5.05	Zr . 00 9	T1 .81	N ₂ .0044	<u>Co</u> 8.75	. 00 23		

week end) standing in air. The order of salt spray or humidity was varied for different tests. Other cycles were exposure to salt spray during working hours alternated with standing in air for nonworking hours. This cycle was 8 hours in salt spray, 16 hours in air for 5 days, and standing in air over weekends. In such tests, the salt solution was allowed to dry on the specimens without rinsing.

RESULTS AND DISCUSSION

Specimens referred to as "bare" were grit blasted and uncoated. Those called "as heat treated" were not given any further processing after the heat treatment to provide the strength level. These specimens were not scaled or otherwise unsatisfactory in appearance to the eye. Heat treatment was accomplished in a neutral, controlled atmosphere furnace with carbon potential similar to the carbon content of the material being treated.

Except for "as heat treated" specimens, which failed in all environments, there was no significant evidence to indicate stress corrosion cracking susceptibility of 4130 steel in the outdoor or humidity cabinet exposures. Specimens in test from 6 months to over a year have not failed. In contrast, the exposures which included salt spray, either as single exposure or as part of a cycle, produced many failures. As shown in Table II, failure times varied among test procedures. The general trend suggested that cycle tests produced failures in less time than single exposure tests.

Behavior of phosphatized specimens as compared with bare specimens gave no easily defined difference in susceptibility. Phosphatized specimen failure times were generally longer, but in one test were shorter than for bare specimens. This does not show any protective characteristic of the phosphate coating with regard to suppression of stress corrosion cracking. At the same time the evidence does not indicate a trend of increased susceptibility as a result of phosphatizing. This latter possibility has been suggested in the literature. The improvement of performance with supplementary coatings over phosphatized steel is an accepted fact. The ability of such coatings to provide a paint base without inducing an increase in stress corrosion cracking may be useful in further work.

Zinc plated specimens suffered from hydrogen embrittlement, and a number were broken within hours or a few days after mounting for test. Those which survived the first few days resisted failure.

TABLE II

EXPOSURE RESULTS OF 4130 BENT BEAM SPECIMENS

	Outdoor	Humidity Cabinet	Salt Spray
As heat treated Blasted-uncoated Zinc phosphatized Zinc plated Zinc dust paint	3/3* 7 wks 1/6 NF** 54 wks 1/6 " " 0/5 " "	6/6 7 days 0/3 NF 25 wks 0/3 " " 0/3 " "	1/2 13 days 2/3 14 wks 2/3 15 wis 1/2 3 days 0/3 NF 25 wks
Cycle Test	104 hrs HC 64 hrs SS	52 hrs SS 52 hrs HC 64 hrs Air	Work days SS Nights and weekends in air
Blasted-uncoated Zinc phosphatized Zinc plated Zinc dust paint	2/3 27 days 1/3 15 wks 2/3 5 hrs 0/3 NF 18 wks	3/3 11 wks 3/3 9 wks	2/2 20 days 2/2 33 days 1/2 7 wks

* 3 breakage, out of 3 specimens in group. ** No failure attributed to stress corrosion.

The zinc dust dispersed paint specimens also resisted failure very well.

The specimens of 6150 and 18% nickel maraging steel, at higher strength levels than the 4130, showed failures in all areas tested. (See Table III) As these materials were received late in the year, only cycle tests were conducted.

The simple use of abrasive grit blasting was an effective pretreatment. This was shown by the greatly increased time to failure between as heat treated and bare specimens for both materials.

The lengthening of failure time is not the final objective of stress corrosion work. Any failure that could be predicted in the expected life of a structure should be considered intolerable. However, failure times do propose directions in which favorable study can be undertaken.

Failure times of phosphatized and zinc dust dispersion coated specimens were longer as compared to the performance of the bare specimens. This suggests again that use of these processes and coatings did not accelerate failure in a susceptible material. It has been noted in the literature that hydrogen liberated during the sacrificial corrosion of such materials as zinc may contribute to brittle fracture failures.

The delay in the failure occurrence as result of abrasive blasting should not necessarily be interpreted as a change in susceptibility to stress corrosion cracking. It is probable that the treatment resulted in a surface barrier effect. For a susceptible material, coatings and surface treatments may act either to intensify or accelerate cracking, or to suppress or retard the cracking process by physical or chemical means. The result noted here indicates the modifying effect of surface treatment should be given further study.

CONCLUSIONS

The alternate use of exposure conditions in cycles as opposed to a single test exposure condition produced more rapid failures. This is desirable for accelerated test purposes.

Specimens of 4130 steel at 204 ksi yield strength, either coated or bare, were not susceptible to stress corrosion cracking when tested at 75% of yield strength in high humidity or in outdoor exposure. They did fail in

TABLE III

EXPOSURE RESULTS OF 6150 AND MARAGING STEEL BENT BEAN SPECIMENS

	52 hrs HC	Work Days SS	Work Days in Air
	52 hrs 55	Nights and Weekends	Nights and Weekends
	64 hrs Air	in Air	in SS
6150			
As heat treated	*	ı	ı
Blasted-uncoated	3/3 2 wks		ı
Zinc phosphatized	9	2/2 21-49 days	1
Zinc dust paint	က	ı	2/2 6 wks
18% nickel			
maraging steel			
As heat treated		1	ı
Blasted-uncoated	3/3 8 days	2/2 30 dajs	ſ
Zinc phosphatized	•	2/2 1-8 wks	1
Zinc dust paint	1	1	1/2 17 days

* 1st figure is number of failures 2nd figure is test specimens in group.

salt spray, or in cycle tests which included salt spray.

Specimens of 6150 at 231 ksi and 18% nickel maraging steel at 316 ksi failed in cycle tests of salt spray. The use of phosphatized coats and zinc dust dispersed paint retarded the failure times as compared to uncoated specimens.

Abrasive blasting of specimens extended the time to failure over "as heat treated" specimens.

Use of zinc phosphatizing did not appear to induce greater susceptibility to failure as compared with uncoated specimens.

LITERATURE REFERENCES

- 1. "Control of Stress Corrosion Interim Report,"
 R. H. Wolff, Rock Island Arsenal Report No. 63-3890,
 26 Nov. 63.
- 2. "Stress Corrosion of Steels for Aircraft and Missiles," E. H. Phelps and A. W. Loginow Corrosion, Vol. 16, No. 7 (1960).
- 3. "Stress Corrosion Cracking of High Strength Steels and Alloys--Artificial Environments," Mellon Institute Contract No. DA 36-034-ORD-3277RD (Frankford Arsenal).

PRIOR REPORT

"Control of Stress Corrosion - Interim Report," R. H. Wolff, Rock Island Report No. 63-3890, 26 Nov. 1963.

65-152

9

		No.	of	Copies
A.	Department of Defense			
	Office of the Director of Defense			
	Research & Engineering			
	ATTN: Mr. J. C. Barrett			
	Room 3D-1085, The Pentagon			
	Washington, D. C.		1	
	Commander			
	Defense Documentation Center			
	ATTN: TIPDR			
	Cameron Station			
	Alexandria, Virginia 22314		20	
B.	Department of the Army - Technical Services			
	Commanding General			
	U.S. Army Materiel Command			
	Room 2502, Bldg. T-7			
	ATTN: AMCRD-RS-CM			
	Washington, D. C. 20315		2	
	Commanding Officer			
	U.S. Army Coating & Chemical Laboratory			
	ATTN: Dr. C. Pickett		2	
	Technical Library		2	
	Aberdeen Proving Ground, Maryland 21005			
	Commanding General			
	U.S. Army Tank Automotive Center			
	ATTN: SMOTA-REM.2		1	
	SMOTA-REM.3		1	
	Warren, Michigan 48090			
	Commanding General			
	U.S. Army Weapons Command			
	ATTN: AMSWE-RD		1	
	AMSWE-PP		1	
	ANSWE-SM		ī	
	Rock Island Arsenal		_	
	Rock Island, Illinois			
	Commanding Officer			
	U.S. Army Production Equipment Agency			
	ATTN: AMXPE			
	Rock Island Arsenal			
	Rock Island, Illinois		1	
			-	

	No. of Copies
Commanding General	
U.S. Army Ammunition Procurement & Supp	oly Agency
ATTN: ORDLY-GTPC	
Joliet, Illinois 60431	1
Commanding General	
U.S. Army Missile Command	
ATTN: Documentation & Technical Info E	Br. 2
Mr. R. E. Ely, AMSMI-RRS	1
Mr. R. Fink, AMSMI-RKX	1
Mr. W. K. Thomas, AMSMI	1
Mr. E. J. Wheelahan, AMSMI-RSM	1
Redstone Arsenal, Alabama 35809	
Commanding Officer	
Frankford Arsenal	
ATTN: SMUFA-1330	1
Library-0270	1
Philadelphia, Pa. 19137	
Commanding Officer	
U.S. Army Materials Research Agency	
Watertown Arsenal	
ATTN: RPD	
Watertown, Mass. 02170	1
Commanding Officer	
Picatinny Arsenal	
ATTN: Plastics & Packaging Lab. PLASTEC	1
Dover, N. J. 07801	•
Commanding Officer	
Springfield Armory	
ATTN: SWESP-TX	
Springfield, Mass. 01101	1
Commanding Officer	
Anniston Army Depot	
ATTN: Chemical Laboratory	
Anniston, Alabama	1
Commanding Officer	
Tobyhanna Army Depot	
ATTN: SMC Packaging and Storage Center	•
Tohuhanna Donngulyania 18466	1

<u>N</u>	o. of Copies
Commanding Officer	
Watertown Arsenal	
ATTN: SMIWT-LX	
Watertown, Mass. 02170	1
Commanda o Caldano	
Commanding Officer	
Watervliet Arsenal	
ATTN: SWEWV-RDR Watervliet, New York 12189	1
watervilet, new fork 12165	
Commanding General	
U.S. Army Munitions Command	
Picatinny Arsenal	
Dover, New Jersey 07801	1
Commandana Oddinan	
Commanding Officer	
U.S. Army Environmental Health Laboratory	•
Army Chemical Center, Maryland	1
Commanding Officer	
U.S. Army Chemical Warfare Laboratories	
ATTN: Technical Library	
Army Chemical Center, Maryland	1
Commondana Office	
Commanding Officer	
Harry Diamond Laboratory	
ATTN: Technical Library	_
Washington, D. C. 20438	1
Commanding Officer	
U.S. Army Engineer Research & Dev. Laboratorie	
ATTN: Chemistry Research Section, Materials	
Ft. Belvoir, Virginia	1
	-
Commanding Officer	
U.S. Army Chemical Research &	
Development Laboratories	
ATTN: Packaging & Materials Research Br.	
Exp. Eng. Div., Dir. of Tech. Service	DS
Army Chemical Center, Maryland	1
Commanding General	
Quartermaster R&D Command	
· ·	
	•
Natick, Massachusetts 01762	1

	NO.	01	Copies
Commanding Officer U.S. Army Prosthetics Research Laboratory Forest Glen, Maryland		1	
Director Joint Military Packaging Training Center ATTN: AMXPT-PT Aberdeen Proving Ground, Maryland 21005		1	
Headquarters U.S. Army Electronics R&D Laboratories ATTN: Materials Branch Fort Monmouth, N. J. 07703		1	
Department of the Army - Other Army Agencies	<u>.</u>		
Commander U.S. Army Research Office Arlington Hall Station Arlington, Virginia		1	
Commanding Officer U.S. Army Research Office (Durham) Box CM, Duke Station Durham, North Carolina		1	
Chief of Research & Development U.S. Army Research & Development Liaison Gro ATTN: Dr. B. Stein APO 757 New York, N. Y.	oup	1	
Commanding Officer U.S. Army Aviation School ATTN: Office of the Librarian		_	
Department of the Navy		1	
Chief Bureau of Naval Weapons Department of the Navy ATTN: RMMP			
Room 2225, Munitions Building Washington, D. C.		1	

C.

	No. of Copies
Commander	
Department of the Navy	
Office of Naval Research	
ATTN: Code 423	
Washington, D. C.	1
Chief	
Department of the Navy	
Bureau of Ships	
ATTN: Code 344	•
Washington, D. C.	1
Commander	
Department of the Navy	
Special Projects Office	
Bureau of Naval Weapons	
ATTN: SP 271	• •
Washington, D. C.	`1
Commander	
U.S. Naval Ordnance Laboratory	
ATTN: Code WM	
White Oak	
Silver Spring, Maryland	1
Commander	•
U.S. Naval Ordnance Test Station	
ATTN: Technical Library Branch	
China Lake, California	1
Chief	
Bureau of Supplies & Accounts	
Department of the Navy	
Code H62, Arlington Annex	
Washington, D. C	1
Director	
Aeronautical Materials Laboratory	
Naval Air Material Center	
Philadelphia 12, Pa.	1
Commander	
U.S. Naval Research Laboratory	
ATTN: Technical Information Center	
Anacostia Station	
Washington, D. C.	1
	

		NO.	01	Copies
	Commander			
	Mare Island Naval Shipyard			
	ATTN: Rubber Laboratory		_	
	Vallejo, California		1	
D.	Department of the Air Force			
	U.S. Air Force Directorate of Research			
	and Development			
	ATTN: Lt. Col. J. B. Shipp, Jr. Room 4D-313, The Pentagon			
	Washington, D. C.		1	
	mashing ton, D. C.		•	
	Wright Air Development Division			
	ATTN: ASRCEE-1		1	
	WWRCO		1	
	Materials Central		1	
	Wright-Patterson Air Force Base, Ohio			
	ARDC Flight Test Center			
	ATTN: Solid Systems Division, FTRSC			
	Edwards Air Force Base, California		1	
	AMC Aeronautical Systems Center			
	ATTN: Manufacturing & Materials			
	Technology Division, LMBMO		_	
	Wright-Patterson Air Force Base, Ohio		2	
	Commanding Officer			
	Brookley Air Force Base			
	ATTN: Air Force Packaging Laboratory		_	
	Alabama		1	
E.	Other Government Agencies			
	Scientific and Technical Information Facilit	ty		
	ATTN: NASA Representative (SAK/DL)	•	1	
	Mr. B. G. Achhammer		1	
	Mr. G. C. Deutsch		1	
	Mr. R. V. Rhode		1	
	P.O. Box 5700			
	Bethesda, Maryland 20014			
	George C. Marshall Space Flight Center			
	National Aeronautics & Space Administration			
	ATTN: M-S&M-M		1	
	M-F&AE-M Huntsville. Alabama 35800		1	
	nunlsville. Alkukma joovu			

	NO.	OI	Copies
Commanding General U.S. Army Weapons Command ATTN: AMSWE-RD Rock Island Arsenal Rock Island, Illinois for release to		3	
Commander British Army Staff ATTN: Reports Officer 3100 Massachusetts Avenue, N. W. Washington 8, D. C.			
Commanding General U.S. Army Weapons Command ATTN: AMSWE-RD Rock Island Arsenal Rock Island, Illinois for release to	,	3	
Canadian Army Staff, Washington ATTN: GSO-1, A&R Section 2450 Massachusetts Avenue, N. W. Washington 8, D. C.			
Prevention of Deterioration Center National Academy of Science National Research Council 2101 Constitution Avenue Washington, D. C.		1	
Chief, Input Section Clearinghouse for Federal Scientific and Technical Information, CFSTI Sills Building 5285 Port Royal Road Springfield Vinginia 22151		: 0	

UNCLASSIFIED 1. Corrosion 2. Stress Corrosion 3. Tang Continue		1. Corrosion 2. Stress Corrosion 3. Zinc Costing	DISTRIBUTION: Copies obtainable from DDC.
ADROCK ISLAND AFRENSI Laboratory, Rock Island, 1111nois CONTROL OF STRESS CORROSION - 2ND INTERIM REPORT, By R. H. Wolff RIA Lab. Rep. 65-152, 18 Jan 65, 16 p. 18cl. tables, (DA Project No. 1CO-24401-Allo, AMC Code tables, (DA Project No. 1CO-24401-Allo, AMC Code	This study of the control of stress correction cracking susceptibility of stress correction of protective contings was dealgned to use abrasive blasted specimens to simulate more nearly the surfaces and conditions of a manufacturing operation. Bent beam specimens of ambufacturing operation. Bent beam specimens of a manufacturing operation. Bent beam specimens of 4130. 6150, and 18% mickel waraging steel were prepared at yield strength levels of 204, 231, and 316 kml respectively for test at 75% of yield strength. Test atmospheres were outdoor, high humidity and salt spray (5%), and cycles of these miternating between salt spray, humidity and air. Cycle tests produced more rapid Zallure than single environments. Abrasive blasting extended the time to cont (over)	AD MOCK Island Arsens! Laboratory, Rock Island, 1111abls CONTROL OF STRESS CORROSION - 2ND INTERIM REPORT, By R. H. Wolff RIA Lab. Rep. 65-152, 18 Jan 65, 16 p. incl. tables, (DA Project No. 100-24401-All0, AMC Code No. 5025.11.84205) Unclassified Report	This study of the control of stress corresion cracking susceptibility of steels by application of protective coatings was designed to use abrasive blasted speciars to simulate more nearly the surfaces and conditions of a manufacturing operation. Best beam specimes of 4130, 6150, and 18% sickel maraging steel vere prepared at year atmospheres sere outdoor. Migh humidity and salt spray (5%), and cycles of these alternating between salt spray, humidity and salt spray (5%), and cycles of these alternating broduced more rapid failure than single environments. Abrasive blasting extended the time to failure as compared to non-blasted uncoated spectons.
UNCLASSIFIED 1. Correston 2. Stress Correston	v p, o	UNCLASSIFIED . Corrosion . Stress . Corrosion . Zinc Costing	DISTRIBUTION: Copies obtainable from DDC.
		_ 4 4 6	0157 470 140 140

The second secon

Abelia C. S. Salabella and State Contract Contract

imens. Coated specimens were electroplated with zinc, zinc phosphatized, or brushed with zinc filled paint. Specimens of 4130 steel had not failed in over a year in outdoor exposure and 6 months in high humidity. Failures were noted with all the materials in cycle tests with indication of extended time to failure as a result of using zinc filled paint.

Amena. Coated apecimens were electroplated with rinc, since phosphatized, or brushed with rinc filled paint. Specimens of 4130 steel had not failed in over a year in outdoor exposure and 6 months in high humidity. Failures were noted with all the majerials in cycle tests with indication of extended time to failure as a result of using rinc filled paint.

imens. Coated specimens were electroplated with sinc, zinc phosphatized, or brushed with zinc filled paint. Specimens of 4130 steel bad not failed in over a year in outdoor exposure and 6 months in high busidity. Failures were noted with all the materials in cycle tests with indication of extended time to failure as a result of using zinc filled paint.

imens. Coated specimens were electroplated with sinc, sinc phosphatized, or brushed with zinc filled paint. Specimens of 4130 steel had not falled in over a year is outdoor exposure and 6 months in high humidity. Pailures were noted with all the materials in cycle tests with indication of extended time to failure as a result of using sinc filled paint.